

Oil Field Environmental Incident Summary

Incident: 20150323144059 **Date/Time of Notice:** 03/23/2015 14:40

Responsible Party: Marathon Oil Company

Well Operator: MARATHON OIL COMPANY

Well Name: JAY SANDSTROM USA 34-31H

Field Name: REUNION BAY

Well File #:

Date Incident: 3/22/2015 **Time Incident:** 18:00

Facility ID Number:

County: MOUNTRAIL

Twp: 151

Rng: 93

Sec: 31

Qtr: SE SW

Location Description: 8 x 40 outside of fence line of location up to the pipeline ROW along northside of location

Submitted By: Callie Karrigan

Received By:

Contact Person: Paul Beacham
Marathon Oil Company
8902 37th St. NW
New Town, ND 58763

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.9	Gallons	0.9	Gallons		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Well was shut-in and remediation initiated. Investigation is ongoing.

Wastes Disposal Location: Minimal affected soil has been remediated on site.

Agencies Involved:

Updates

Date: 3/23/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.